

FORK LIFT BROOM ATTACHMENT


FLBRM60, FLBRM72, (5)FLBRMBR
800109, 800110, 800112



Operator's Manual

Read the Operator's Manual entirely. When you see this symbol, the subsequent instructions and warnings are serious follow without exception. Your life and the lives of others depend on it!

PARTS DIAGRAM / EXPLODED VIEW



KEY	DESCRIPTION	QTY FLBRM60	QTY FLBRM72
(1)	BROOM HEAD	x1	x1
(2)	FORK CLAMP	x2	x2
(3)	SIDE PANEL	x2	x2
(4)	M10-1.5 BOLT	x4	x4
(5)	M10 SPRING WASHER	x4	x4
(6)	BRISTLE STRIP	x40	x48
(7)	TIGHTENING BRACKET	x2	x2
(8)	CHAIN	x2	x2

REPLACING YOUR BRISTLE STRIPS

FLBRMBR consists of five replacement bristle strips

- To replace your Forklift Broom Attachment's bristle strips, unscrew one of the M10-1.5 BOLTS (4) on a SIDE PANEL (3), slide the SIDE PANEL (3) up, and replace the bristle strips.
- Do not forget to lower the SIDE PANEL (3) and screw in the M10-1.5 BOLT (4) once you are finished replacing your bristle strips.



ACKNOWLEDGEMENT OF RISK AND RELEASE OF LIABILITY

The use of any equipment, including this one, involves the potential risk of injury. Apart from any warranty claim that might be presented for a claimed defect in material or workmanship of the product, you accept and assume full responsibility for any and all injuries, damages (both economic and non-economic), and losses of any type, which may occur, and you fully and forever release and discharge Titan, its insurers, employees, officers, directors, associates, and agents from any and all claims, demands, damages, rights of action, or causes of action, present or future, whether the same be known or unknown, anticipated, or unanticipated, resulting from or arising out of the use of said equipment.

This equipment must be used with care by capable and competent individuals under supervision, if necessary.

WARNING



Do not overfill! Mower should be level when checking oil in gear box.



some activities might be able to cause electric shock



Sharp objects may be involved.
Use protective cover during maintenance.

TITAN LIMITED WARRANTY: TERMS, EXCLUSIONS AND LIMITATIONS OF REMEDIES

This product comes with a one (1) year limited warranty that can be found at www.palletforks.com/warranty.html. Please review the same for all details regarding the Titan Limited Warranty.

THE TITAN LIMITED WARRANTY FOUND AT WWW.PALLETFORKS.COM/WARRANTY.HTML IS EXCLUSIVE AND IS IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY AND/OR FITNESS FOR A PARTICULAR PURPOSE, EACH OF WHICH IS HEREBY DISCLAIMED.



NEED HELP? CONTACT US FIRST.

1-800-605-7595

info@palletworks.com
www.palletforks.com

© 2025 Titan Brands